

INSPECTION RECORD
SOLID MINERALS

300330 Jgm

DMO Albuquerque STATE NM DATE OF INSPECTION March 24, 1983

SERIAL NUMBER OF TRACT	HOLDER OF PRIMARY TRACT INTEREST	TRACT STATUS	NUMBER OF INSPECTIONS	HOURS OF INSPECTION ONSITE/TOTAL	COMMODITY	TRACT TYPE
COLUMN 1	COLUMN 2	COLUMN 3	COLUMN 4	COLUMN 5	COLUMN 6	COLUMN 7
NOO-C-14-20- 5681	TEDCO	Exploration	1	1.4 / 4.6	Uranium	Lease
				/		
				/		
				/		
				/		
				/		
				/		
				/		
				/		
				/		

TYPE OF INSPECTION (CHECK ONE) / / MINE / X / EXPLORATION / / MINE ABANDONMENT
/ / TECH EXAM, EA / / INACTIVE / / OTHER

PURPOSE OF INSPECTION To become familiar with lease area, check overall condition of lease,
and to check on drilling which was to have begun 03/21/83.

BRIEF DESCRIPTION OF INSPECTION Lease was inspected by truck and on foot. TEDCO's 1983 drillin
is authorized under a previously-approved supplemental exploration plan. No new drilling was
found (TEDCO will be contacted). Photos show previous drilling (areas not completely re-

MINE NAME _____ DESIGNATED OPERATOR _____ claimed)

DATE ORIGINAL MINE PLAN SUBMITTED _____ DATE ORIGINAL MINE PLAN APPROVED _____

DATE MODIFIED MINE PLAN SUBMITTED _____ DATE MODIFIED MINE PLAN APPROVED _____

IF APPROVED PLAN IS PENDING MODIFICATION, GIVE BRIEF DESCRIPTION OF MODIFICATION: _____

DATE ORIGINAL EXPL. PLAN SUBMITTED 04/09/76 DATE ORIGINAL EXPL. PLAN APPROVED 06/28/76

DATE MODIFIED EXPL. PLAN SUBMITTED 03/11/81 DATE MODIFIED EXPL. PLAN APPROVED 04/06/81

BLM INSPECTOR(S) AND TITLES(S) John M. Andrews, Jr., Environmental Scientist

SURFACE MANAGEMENT AGENCY FOR TRACT(S) Bureau of Indian Affairs

NAME, TITLE, AND OFFICE OF SMA PERSONNEL PARTICIPATING IN INSPECTION None

NAME, TITLE, AND OFFICE OF OSM OR REGULATORY AUTHORITY PERSONNEL PARTICIPATING IN INSPECTION
None

NAME, TITLE, AND OFFICE OF COMPANY REPRESENTATIVE(S) PARTICIPATING IN INSPECTION None

HOURS OF OFFICES TIME (PRE-INSPECTION) PREPARING FOR INSPECTION 0.5

HOURS OF OFFICES TIME (POST-INSPECTION) REPORTING ON INSPECTION 0.5

TOTAL TRAVEL TIME 2.2 TOTAL OFFICE TIME 1.0

WAS A CONDITION OF NONCOMPLIANCE ENCOUNTERED DURING INSPECTION? / / YES / X / NO
IF YES, PREPARE NONCOMPLIANCE REPORT

WAS AN UNDESIRABLE EVENT ENCOUNTERED DURING INSPECTION? / / YES / X / NO
IF YES, PREPARE UNDESIRABLE EVENT REPORT

PERSONNEL RESPONSIBLE FOR CONDUCTING INSPECTION

John M. Andrews, Jr.

RECEIVED

cc: Area Director, Navajo Area, BIA
Superintendent, Eastern Navajo, BIA
DMM-Mining, SCR
IR File
Chrono

31 MAR 1983

APR 8 1983

AREA BRANCH OF
REAL PROPERTY MGMT.




Photo 1 1982 drill hole on lease -5681. Hole is in access road.



Photo 2 1982 drill hole about 200 feet west of hole in Photo 1. Access road is still being used so site reclamation is not complete.